

Fault Report

Customer Name MARSELLA	Date: 01/4/26
Customer Reference: 26818	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: <input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No
Fault Description: <ul style="list-style-type: none">◦ INCREASE LIVING ROOM BLIND BY 35mm (2055 PROP) (SPLIT)◦ INCREASE DROP OF BEDROOM BLIND TO 1155mm (GOING TO RIGHT / NOT SPLIT)◦ RIGHT END SLAT HITS THE CHAIN CUP / WONT CLOSE.	
Action to correct: REMAKE BLINDS	
Problem fixed on site: <input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No	
Further action required: REMAKE BLINDS	