

Fault Report

Customer Name WRIGHT	Date; 20/04/26
Customer Reference: 26830	Fitter MICHAEL
Salesperson: KEVIN	Salesperson called: Yes/No
Fault Description: Mismeasure Blind MEZZANINE (4)	
Action to correct: cut down/remake @ 1130 x 765mm	
Problem fixed on site: Yes (No)	
Further action required: Yes remake/cut down & return to f.v.	