

# Fault Report

Customer Name WRIGHT	Date: 17/11/28
Customer Reference: 26561	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Rail NO1 too tight can't turn slats easily	
Action to correct: Remake @ 2957 Recess	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes remake & swap over the rails.	