

SB5698

STEEL

SCOTBLINDS - FAULT SHEET

CUSTOMER DETAILS:

ID: SB5698
NAME: Steel
ADDRESS: 69 Anderson Crescent
Shieldhill, Falkirk
TELEPHONE NO: 07895632341
EMAIL: _____
DATE REPORTED: 21-10-23

ISSUE REPORTED: _____
Replacement Perfect fit not Running
Square,
rubbing against brackets and fraying
fabric
this is already her second visit ï

REMEDIAL ACTION REQUIRED: _____
new Perfect fit required
395w x 948 drop
Polaris Blout charcoal

OFFICE USE
CUSTOMER CONTACT LOG: _____

