

SB6659R

SB 612~~2~~

## Fault Report

MACINTOSH/R

Customer Name: MACINTOSH	Date: 10 / Nov / 23
Customer Reference: 6120	Fitter: Dylan
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: cassete roller - Bath 760 by 1130	
Fault Description: cassete got scratches.	
Action to correct: Replae cassete casing.	
Problem fixed on site: Yes/No	
Further action required:	