

SB6570R

SB 6043  
BUSBY / R.

# Fault Report

Customer Name: BUSBY	Date: 9-11-23.
Customer Reference: SB6043	Fitter: GIREME
Salesperson: GIREME	Salesperson called: Yes/No
Blind Type and number: INFILL CARD ON 2 x BLINDS	
Fault Description:  NEED NEW INFILL CARD FOR 2 x ROOF BLINDS. (GET FROM JAMES)	
Action to correct:  BOOK FOR GIREME TO GO DO.	
Problem fixed on site: Yes/No	
Further action required:	