



SB 6166  
PENMAN/R

# Fault Report

Customer Name: Penman	Date: 21/11/23
Customer Reference: 6166	Fitter: Dylan
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: verticals	
Fault Description: Blind slats sit fine on 1 side (RH) But on (LH) side sit on ledge	
Action to correct: take <del>ten</del> <sup>9</sup> mm of blind slats S/B 10mm AS PER KATE.	
Problem fixed on site: Yes/No	
Further action required:	