

✓ SB 6164
DAWSON/R.

Fault Report

SCOT Blinds

Customer Name: Dawson	Date:
Customer Reference: 6164	Fitter: Dylan.
Salesperson: David.	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: Verticals X2.	
Fault Description: 2 vertical Blinds joined, but has a gap inbetween.	
Action to correct: Collect head rails from customer and alter to have an over lap to cover gap in the middle of the joining blinds.	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:	