

SB 6251
LANDSDOWN / R

Fault Report

Customer Name: LANDSDOWN	Date: 5-2-24
Customer Reference: SB 6251	Fitter: GRENNE
Salesperson: DAVID	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: PERFECT FIT VENETIAN RIGHT DOOR	
Fault Description: SLAT LOOKS DIFFERENT TO LEFT DOOR.	
Action to correct: REMAKE BOTH ON SAME BATCH.	
Problem fixed on site: Yes/No	
Further action required:	