

Fault Report

ONG 908R1

SB 6303
WALLS/R

FITTER NAME: David	FITTING DATE: 30/8/24
Customer Name: Walls	
Customer Ref: 6303	
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Vertical track	
Problem fixed on site: No	
Fault Description Washers that hold the bar in place inside the track are missing and the bar keep slipping out	
Action to Correct:- Need washers to put onto the bar to hold it in place	