

SB 6303
WALLS/R

SB6908R

Fault Report

Customer Name: Walls	Date: 01/04/24
Customer Reference: 6303	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: vertical	
Fault Description: Vertical slats hitting window handles	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: Need 7 100mm long face fix vertical brackets to bring track out further	