

SB 6325
JOHNSON /R

Fault Report

SB7042R

Customer Name: JOHNSON	Date: 16 - 05 - 2024
Customer Reference: SB 6325 JOHNSON	Fitter: DAVID H
Salesperson: DAVID H	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: PERFECT FIT VENETIAN (1)	
Fault Description: DAMAGE (SCUFF) TO BOTTOM LEFT FRAME. 404 X 910	
Action to correct: PART ABOVE TO BE REPLACED	
Problem fixed on site: Yes/No	
Further action required: <u> </u>	

