

Fault Report

FITTER NAME: David	FITTING DATE: 16/9/24
Customer Name: Parker	
Customer Ref: 6670 6600	
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Shutter 1	
Problem fixed on site: Yes/No	
Fault Description Bottom frame has a chip on it (Pictures emailed in)	
Action to Correct:- New bottom part of the frame needed	