

SB 6829
MARTIN / R
SB 7301R

Fault Report

FITTER NAME: David	FITTING DATE: 26/08/24
Customer Name: Martin	
Customer Ref: 6829	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Vertical slats	
Problem fixed on site: Yes/No	
Fault Description Slats made recess size instead of hem to hem	
Action to Correct:- new slats made hem to hem size 1930 drop	