

SB 6825  
FOULSER/R

# Fault Report

<b>FITTER NAME:</b> David	<b>FITTING DATE:</b> 23/9/24
Customer Name: Foulser	
Customer Ref: 6825	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number:  curtain	
Problem fixed on site: Yes/No	
<b>Fault Description</b>  Customer isn't happy that there is a join in the curtains. I explained to him that it's because of the size there has to be a join but he has said it wasn't explained to him when he was sold them.  Pictures taken and customer looking to be contacted about them.	
<b>Action to Correct:-</b>  Nothing we can do due to width of curtain	