

SB 7336/R
6865

Fault Report

ON 7336

FITTER NAME:	FITTING DATE:
Customer Name: MR ALAN	
Customer Ref: SB 7336 6865	
Salesperson: RONNIE	Salesperson called: Yes/ No
Blind Type and number: 1 X VERTICAL	
Problem fixed on site: Yes/No NO	
Fault Description HEADRAIL DAMAGED AS ITEMS HAD BEEN SAT ON TOP OF HEADRAIL WHEN DELIVERED TO SHOWROOM.	
Action to Correct:- NEW HEADRAIL REQUIRED.	