

SB 6916
BIRCH IR

Fault Report

SB 7358R

FITTER NAME: David	FITTING DATE:
Customer Name: Birch	
Customer Ref: 6916	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Perfect fit hall right 3841038 was	
Problem fixed on site: Yes/No	
Fault Description Mismeasure	
Action to Correct:- blind should be 389x1040	