

JB 6837
SNEEDDON /R

Fault Report

SB 7319R

FITTER NAME: Collected from showroom	FITTING DATE: Customer fitted
Customer Name: Sneddon	
Customer Ref: 6837	
Salesperson: /	Salesperson called: Yes/No
Blind Type and number: 2 x Roman blinds	
Problem fixed on site: Yes/No	
Fault Description 2 x Roman blinds came to be re-corded but we have taken the chains off and changed to motorised.	
Action to Correct:- Change back to chain operation	