

SB 6979  
WINNING/R

# Fault Report

SB 7476R

<b>FITTER NAME:</b> David	<b>FITTING DATE:</b> 11/10/24
<b>Customer Name:</b> Winning	
<b>Customer Ref:</b> 6979	
<b>Salesperson:</b> Ronnie	<b>Salesperson called:</b> Yes/No
<b>Blind Type and number:</b>  Pf roller	
<b>Problem fixed on site:</b> Yes/No	
<b>Fault Description</b>  Top left hand corner part with the roller mechanism is broken.	
<b>Action to Correct:-</b>  New part needed and will change it on site.	