

SB 7724
SCOTT/R

FITTER NAME: David	FITTING DATE: 23/04/2025
Customer Name: Scott	
Customer Ref: 7724	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Bedroom shutter	
Problem fixed on site: Yes/No	
Fault Description Window very uneven and large gaps at one side	
Action to Correct:- Cover strips needed. 5x 40x 1825 5x 30 x1040 (2 needed)	