

SB 7166  
RITCHIE/R

# Fault Report

Customer Name: <u>RITCHIE</u>	Date: <u>11-7-25</u>
Customer Reference: <u>7166</u>	Fitter: <u>DAVID</u>
Salesperson: <u>RONNIE</u>	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: <u>KITCHEN VERTICAL TRACK</u>	
Fault Description: <u>TRACK IS TOO LONG</u>	
Action to correct: <u>TRACK TO BE CUT DOWN 1725 ACCESS</u>	