

SB 7960.
Campbell IR

Fault Report

Customer Name: CAMPBELL	Date: 12-11-23
Customer Reference: 7960	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: (Yes/No)
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: ROLLER CHAINS	
Fault Description: CHAIN HAS BEEN MADE TOO SHORT CHAIN IS BLACK CHROME AND ONLY HAVE STANDARD CHROME CHAIN SO COULDN'T FIX THE ISSUE	
Action to correct: NEW CHAIN AT ORDER SIZE ASKED FOR ON ORDER FORM ?	

ORDER TOTAL = £159

24/10/23.

