

# Fault Report

|  |   |
|--|---|
| Customer Name: <i>Liston</i>   | Date: <i>2/3/22</i>   |
| Customer Reference: <i>4045</i>  | Fitter: <i>Camelton</i>                                     |
| Salesperson: <i>Camelton</i>   | Salesperson called: <input checked="" type="radio"/> Yes/No |
| Blind Type and number: <i>Intu ven</i>   |   |
| Fault Description: <i>Blind k measured wrong</i><br><br><i>853 x 1305</i><br><u>          </u> |   |
| Action to correct: <i>new size taken + James says headrail can be cut down in size</i>         |   |
| Problem fixed on site: Yes/ <input checked="" type="radio"/> No                                |   |
| Further action required: <i>Call customer to let know if Friday is OK</i>                      |   |