

Rain 6572
McDonnell . R.

Fault Report

Customer Name: McDonnell	Date: 29/6/22
Customer Reference: 6572	Fitter: Cameron
Salesperson: David	Salesperson called: Yes/No <input checked="" type="checkbox"/>
Blind Type and number: Roller 1	
Fault Description: Blind no 5 damage	
Action to correct: Remake & Reordered	
Problem fixed on site: Yes/No	
Further action required: *Blind Re-Ordered*	