

# Fault Report

Customer Name: Brydon	Date: 30/5/22
Customer Reference: 4209	Fitter: Camelot
Salesperson:	Salesperson called: Yes/No <input checked="" type="checkbox"/>
Blind Type and number: 4 P/R 25mm	
Fault Description: Measured 100mm to short on drop.	
Action to correct: Returned to factory	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/>	
Further action required:	