

# Fault Report

Customer Name: <i>Kareli</i>	Date: <i>16/6/22</i>
Customer Reference:	Fitter: <i>Camron</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>Pelmet</i>	
Fault Description: <i>Pelmet has no mitred ends Could have mitred on site But could make it smaller + Pelmet wood prone to splintering</i>	
Action to correct:	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required: <i>New pelmets to be reordered (1870)</i>	