

Rain 6473
Narrowmore

Fault Report

Customer Name: <u>Narrowmore</u>	Date: <u>5/7/22</u>
Customer Reference:	Fitter: <u>Cameron</u>
Salesperson: <u>David</u>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number:	<u>Motorised Keller</u>
Fault Description:	<u>Both head boxes made wrong</u> <u>Both are 2509 wide</u>
Action to correct:	<u>Remake both in correct size</u> <u>@ 1 - 2500 2 - 2495</u> <u>Both recess</u>
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:	

