

Fault Report

Customer Name: KENT	Date: 31-8-22
Customer Reference: 5441	Fitter: GRAEME
Salesperson:	Salesperson called: Yes/No
Blind Type and number: 2x P-FIT ROLLERS	
Fault Description: FABRIC HAS CONED AND ALL CREASED.	
Action to correct: CAN WE REMOVE ON CHAIN SYSTEM?	
Problem fixed on site: Yes/No	
Further action required:	