

# Fault Report

Customer Name: GIBSON	Date:
Customer Reference: 5806	Fitter: DAVID
Salesperson: A. RAME	Salesperson called: Yes/No
Blind Type and number: CURTAIN	
Fault Description: CUSTOMER NOT HAPPY WITH HOW THE CURTAIN IS STRETCHED/SITS	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	