

Fault Report

Customer Name: <i>McFarlane</i>	Date:
Customer Reference: <i>4376</i>	Fitter: <i>CP</i>
Salesperson: <i>CP</i>	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: <i>Roller</i>	
Fault Description: <i>Remake kitchen roller 5mm smaller on width Take bracket covers</i>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	