

# Fault Report

|  |                                   |
|--|-----------------------------------|
| Customer Name: <u>Bower</u>                                      | Date: <u>11-10</u>                |
| Customer Reference:<br><u>4605</u>                               | Fitter: <u>DAVID</u>              |
| Salesperson:<br><u>CAMDEN</u>                                    | Salesperson called: <u>Yes/No</u> |
| Blind Type and number:<br><u>PFT 1+2</u>                         |                                   |
| Fault Description:<br><u>MIS MEASURED</u>                        |                                   |
| Action to correct:   |                                   |
| Problem fixed on site: <u>Yes/No</u>                             |                                   |
| Further action required:<br><u>RE MADE AT 1773 DROF FOR BOTH</u> |                                   |