

Fault Report

Customer Name: <i>Stroud</i>	Date:
Customer Reference: <i>4430</i>	Fitter: <i>CP</i>
Salesperson: <i>CP</i>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: <i>1 PF</i>	
Fault Description: <i>PF Roller made in wrong fab</i>	
Action to correct: <i>Remake in correct time</i>	
Problem fixed on site: Yes/No	
Further action required:	