

ED 4407

Fault Report

Customer Name: <i>W. K. R.</i>	Date:
Customer Reference: <i>4407</i>	Fitter: <i>CP</i>
Salesperson: <i>CP</i>	Salesperson called: Yes/No
Blind Type and number: <i>1 Pf</i>	
Fault Description: <i>Corner covers on Pf Need to be cut down</i>	
Action to correct: <i>I will cut them down unless there slimmer ones Available</i>	
Problem fixed on site: Yes/No	<input checked="" type="radio"/>
Further action required:	