

RAIN 7249  
LAWSON.

# Fault Report

Customer Name: LAWSON	Date: 12-01-23
Customer Reference: 7249	Fitter: CARM
Salesperson: CARM	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: FAUX WOOD / LOUNGE (1)	
Fault Description: MADE TO SHORT ON DROP 1805 x 1440 (WRONG DROP) CORRECT SIZE ON BOX JUST MADE SHORT	
Action to correct: REORDER AT SIZE GIVEN 1805 x 1540	
Problem fixed on site: Yes/No	
Further action required:	