

RAIN 7185
HASLAM.

Fault Report

Customer Name: HASLAM	Date: 16-1-23
Customer Reference: 7185	Fitter: GARY
Salesperson: GARY	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input checked="" type="checkbox"/>	
Blind Type and number: 3 LOUNGE.	
Fault Description: CUSTOMER NOT HAPPY WITH POSITION OF ORIGINAL BLINDS	
Action to correct: REWORK BLIND AT DIFFERENT SIZE, 530 x 1260 795 x ↓ 535 x ↓	
Problem fixed on site: Yes/ No	
Further action required:	