

RAIN 7300
HIGGINS.

Fault Report

Customer Name: HIGGINS	Date: 02-02-23
Customer Reference: 7300	Fitter: GARY
Salesperson: GARY	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: 1 ROLLER	
Fault Description: ROLLER FOR BED BEEN MADE IN SPLASH SNOW. SHOULD BE BELLA SNOW	
Action to correct: REMAKE BLIND IN BELLA SNOW	
Problem fixed on site: Yes/No <u>No</u>	
Further action required:	