

ED 4521

STEEL,

Fault Report

Customer Name: STEEL	Date: 07-03-23
Customer Reference: 4521	Fitter: GARY
Salesperson: /	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: 1 x VISION	
Fault Description: FRAMING ON FABRIC	
Action to correct: TO BE RECOVERED FOR SIZES ON BLIND IN FACTORY	
Problem fixed on site: Yes/No	
Further action required:	