

RAIN 7171
BEATTIE

Fault Report

Customer Name: BEATTIE	Date: 18-04-23
Customer Reference: 7171	Fitter: GARY
Salesperson: GARY	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: 1 x WOOD	
Fault Description: LOUNGE WOOD AS SPLITS IN SLATS. ⚡	
Action to correct: PLEASE REORDER LOUNGE 2400 x 1640	
Problem fixed on site: Yes/No (No circled)	
Further action required:	