

RAIN 7500  
MCKINTOSH

Customer Name: Mackintosh	Date: 09-06-23
Customer Reference: 7500	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No —
Blind Type and number: Perfect fit cut out	
Fault Description: Cut out for handle on wrong side of frame	
Action to correct: Recut leg on the right side of frame	
Problem fixed on site: No	
Further action required:	

# Fault Report