

EO 4546
BIRNIE / 23.

Fault Report

Customer Name: <u>BIRNIE</u>	Date: <u>21-6-23</u>
Customer Reference: <u>4546</u>	Fitter: <u>DAVID</u>
Salesperson:	Salesperson called: <u>Yes/No</u>
Blind type and number: <u>PATIO RIGHT DOOR</u>	
Fault Description: <u>MATERIAL CRACKED</u>	
Action to correct:	
Problem fixed on site: <u>Yes/No</u>	
Further action required: <u>NEW BLIND NEEDED</u>	