

ED 4769

VAN DER VELDEN

# Fault Report

Customer Name: VAN DER VELDEN	Date: 19/07/2023
Customer Reference: 4769	Fitter: GARY
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: ALL PF ROLLERS	
Fault Description:  ALL PERFECT FIT ROLLERS HAVE HOLES IN FABRRIC	
Action to correct:  RE-MAKE ALL 4 PERFECT FITS	
Problem fixed on site: Yes/No	
Further action required:  BLIND 1 - LH CHAIN - CHAIN FULL LENGTH OF DROP BLIND 2 - FR SIZE (813 X 996) TENTIONED BLIND 3 - RH CHAIN - CHAIN FULL LENGTH OF DROP BLIND 4 - AS IS ON SYSTEM	