

RAIN 7253
SENSOM 1/21

Fault Report

Customer Name: SENSOM	Date: 20-9-23
Customer Reference: 7253	Fitter: GRAEME.
Salesperson:	Salesperson called: Yes/No
Blind Type and number: ITEM 2 PANEL 3.	
Fault Description: DAMAGED.	
Action to correct: REMOVE Panel 3.	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required:	