

KAIN 7773

KELLOCK / R

ONISOSOR

Customer Name: Kellock	Date: 09/09/23
Customer Reference: 7773	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No
Blind Type and number: Faux wood. Blind 5 (utility)	
Fault Description: Deformed and webbing is wrong	
Action to correct: Rework blind	
Problem fixed on site: No	
Further action required: No	

Fault Report