

RAIN 8096
CLARK / R

Fault Report

FITTER NAME: GRAENE	FITTING DATE: 2-12-24
Customer Name: CLARK	
Customer Ref: 8096	
Salesperson: GARY	Salesperson called: Yes <input checked="" type="radio"/> No
Blind Type and number: BATH WOOD.	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Fault Description CUSTOMER WANTS THIS CHANGED TO A METAL VENETIAN. 0952. WOODEN BLIND CORDS ARE WRONG + BLIND BOUS WHEN RAISED.	
Action to Correct:- REMOVE AS A METAL VENETIAN IN 0952.	