

RAIN 8103  
GORDON / R

Customer Name: Gordon	Date: 20/05/23
Customer Reference: 8103	Fitter: Gary
Salesperson: Greame	Salesperson called: Yes/No Yes
Blind Type and number: vertical	
Fault Description: Headrail was made to wide.	
Action to correct: Went to factory and got it cut down (spoke with Greame to ok this as job was in wishaw and customer was only available for that time for fitting)	
Problem fixed on site: Yes	
Further action required: No	

# Fault Report