

KAIN 8176
ALLISON/R.

Fault Report

FITTER NAME: Gary	FITTING DATE: 15/7/24
Customer Name: Carol Allison	
Customer Ref: 8176	
Salesperson: Gary	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Roller 2 - Bedroom	
Problem fixed on site: Yes/No	
Fault Description Blind miss-measured	
Action to Correct:- Re-make @ 1415 wide (recess)	