

RAIN 8277
GILLIAN

Fault Report

FITTER NAME: Ross	FITTING DATE: 7/10/24
Customer Name: Gillian	
Customer Ref: Rain 8277	
Salesperson: Rennie	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Roman	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Fault Description Control broken in transit	
Action to Correct:- Replace control.	