

EO 5088
MCDONALD/K

Customer Name: McDONALD	Date: 22/08/23
Customer Reference: 5008	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No
Blind Type and number: 3 X PERFECT FIT ROLLERS	
Fault Description: BLINDS ARE BAGGY AND =NOT SITTING CORRECTLY	
Action to correct: IN FACTORY FOR INSPECTION	
Problem fixed on site: No	
Further action required: No	

Fault Report