

RAIN 8586

THOMSON/R  
ON 84269R

Customer Name: Thomson	Date: 14/05/25
Customer Reference: 8586	Fitter: Gary
Salesperson: Ronnie	Salesperson called: No
Blind Type and number: Verticals	
Fault Description: All slats are welded squint. Pictures sent in via email.	
Action to correct: Remake all slats please	
Problem fixed on site:	
Further action required:	

# Fault Report

