

EAIN 8855
HAMILTON/R
ON 86624R

Customer Name: Hamilton	Date: 12/05/25
Customer Reference: 8855	Fitter: Gary
Salesperson: Gary	Salesperson called: No
Blind Type and number: Vertical	
Fault Description: 2 Slats are broken at top. Hard PVC fault	
Action to correct: Order 2 replacments	
Problem fixed on site:	
Further action required:	

Fault Report

